



UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
DIXIE RESOURCE AREA OFFICE
345 EAST RIVERSIDE DRIVE SUITE 102
ST. GEORGE, UTAH 84770



SENDERS INFORMATION	RECEIVERS INFORMATION
Candara Fax #: (001) 400 3250	Receives Pax #. 307-5440
From: Larry Gore	To: Wayne Hedberg
Senders Office: Dixie Resource Area	Receivers Office: UDOGM

Number of Pages (Including Transmittal Sheet): 2

## Comments:

Letter from Pete Stevenson re: the EPA testing at silver Reef.







999 18th STREET - SUITE 500 DENVER, COLORADO 80202-2466

Sept 30, 1997


Ref: 8EPR-ER

Mr. Larry Gore
U.S. Department of the Interior
Bureau of Land Management
Dixie Resource Area
225 North Bluff St.
St. George, Utah 84770

Dear Larry:

Burewort Land Macagement Dile Resource Mos

OT 11 4 1997



I received your letter and realized I was remiss in not providing results of our inspection of the cap at the Leeds Silver site that was conducted on February 18, 1997 in conjunction with an inspection at another site nearby. I have asked Clark Whitlock of the Bureau of Reclamation to fax or send you the sample results from the water samples we collected.

Prior to February 18, 1997 there was a 2"+ precipitation event. The cap experienced some minor wash out at the lower end, and the berm had eroded about two inches deep in a couple of places. The surface drain worked and the sump only had about one foot of water in it, which we sampled. We also sampled the downgradient monitoring well and the well near the sump which was completed beneath the asphalt lined hear. There was approximately 10' of water in this well. The sample results indicated no significant changes in groundwater quality.

During the week of November 17, 1997 I will be near the site conducting a sampling activity, and will stop by the Leeds Silver site to check water levels in the wells and sump and inspect the cap. If you have any questions, please call me at (303) 312-6799.

Sincerely,

Peter D. Stevenson, OSC Emergency Response Program